ADVANCE PROCESS SUPPLY COMPANY

MATERIAL SAFETY DATA SHEET

FOR COATINGS, RESINS AND RELATED MATERIALS

		=====================================
	DATE OF PREP IN COMPLIANCE WITH OSHA 1910-1200	HAZARD COMM. STD.
	MANUFACTURER ===	
	NAME : ADVANCE PROCESS SUPPLY COMPANY	EMERGENCY TELEPHONE NO.
	ADDRESS : 400 N. NOBLE STREET ADDRESS :	DAY: 312/829-1400
	CITY,STATE : CHICAGO IL	NIGHT: 312/829-1400
	ZIPCODE : 60622	
	======================================	T ====================================
		=======================================
	NUMBER : PLAX-228	H M I S Code
	NAME : PLASTISOL OPAQUE GOLD	Health : 1
	CLASS : VINYL COPOLYMER	Flammability : 1
		Reactivity : 1
		Protective Equip : I
	======================================	
	======================================	
	INGREDIENT ! % % !	C.A.S LEL UAP. PRES
	MATERIAL DESCRIPTION ! BY WT. ! BY VOL !	REGISTRY NO. ! ! mm.Hs @20
	,我们就是我们的"我们"的"我们"的"我们"的"我们"的"我们"的"我们"的"我们"的"我	
		39393-37-8 ! N/A! 9.0
-		
_	======================================	
	BOILING RANGE : 252 N/A DEG. !.FREEZING PO	
	VAP. PRES. (020 des. C): N/A mm! VAPOR DENS	DINT: N/A des. F
	SPECIFIC GRAVITY: 1.278 SOLUBILITY	III (HIK=I) + N/A EST.
	SPECIFIC GRAVITY: 1.278 ! SOLUBILITY EVAPORATION RATE: Slower ! % VOLATILE	RY UNLIME ! A.AA
	(relative to n-butsl acetate) !	wi valuant VIVV
	APPEARANCE & ODOR : YELLOW PASTE - MILD ODOR	Superfund Records Center
		Superfund Records Center

Superfund Records Center SITE: $\frac{|V_i|^2}{|V_i|^2} \in H$ BREAK: $\frac{|V_i|^2}{|V_i|^2} \in H$ OTHER: $\frac{|V_i|^2}{|V_i|^2} \in H$

SDMS DocID

548852

```
FLASHPOINT :
                                 440.0 Des. F.
                   ! FLAMMABLE LIMITS :
(Method Used) SETA FLASH
FLAMMABILITY CLASSIFICATION
                                    N/A
                                        N/A
  OSHA : COMBUSTIBLE LIQUID - CLASS III B
  DOT
    : NOT REGULATED
EXTINGUISHING MEDIA:
 Water fos
 Alcohol foam.
 Carbon dioxide (CO2).
 Dry chemical.
 POTASSIUM BICARBONATE
SPECIAL FIRE FIGHTING PROCEDURES :
 Use water fos to cool containers.
 Use water spray to dilute spills.
 Wear protective clothing.
 Shut off all power to the area.
UNUSUAL FIRE AND EXPLOSION HAZARDS
 Dangerous when heated.
 liquid is irritating to eyes and skin.
! LD50(mg/kg) !LD50(ppm
---- INGREDIENT ---- !
                 !BURNS!EFA ! - TLV (twa) - ! (rat)! (rbt)! (rat)
MATERIAL DESCRIPTION ! PEL!SKIN !LIST! ms/m3 ! PPm ! ORAL !DERMAL! INHAL
              ! N/A! No ! Yes! N/A!
                              N/A!
                                   N/A!
THRESHOLD LIMIT VALUE
                 SEE SECTION V
EFFECTS OF OVEREXPOSURE :
 Vapors may irritate the eyes.
 Vapors may irritate respiratory tract.
EMERGENCY AND FIRST AID PROCEDURES
 Move to fresh air.
 Flush eyes with water for 15 min.
 Wash skin with soap and water.
 Remove contaminated clothing.
 Call physician immediately.
STABILITY: Stable
STABILITY CONDITIONS TO AVOID :
 Extreme heat.
 ELEVATED TEMPERATURES
INCOMPATABILITY (MAT'LS TO AVOID)
 EXCESSIVE HEAT
HAZARDOUS DECOMPOSITION PRODUCTS:
 Acrid smoke.
 Oxides of carbon.
 VARIOUS HYDROCARBONS
 NOXIOUS GASES
HAZARDOUS POLYMERIZATION : May occur
POLYMERIZATION CONDITIONS TO AVOID
```

Excessive heat.

```
SECTION VIII -- SPILL OR LEAK PROCEDURES ==============
STEPS FOR MATERIAL SPILLAGE :
  Absorb w/sand & dispose of in approved manner
  LARGE SPILLS-COLLECT FOR DISPOSAL.
  KEEP MATERIAL OUT OF SEWERS, STREAM, ETC.
 WASTE DISPOSAL METHOD :
  Incinerate in approved manner.
  Landfill in accordance with local, state and federal ress.
  Dispose of in accordance with local regulations.
 RESPIRATORY PROTECTION :
  Vapor respirator.
VENTILATION:
  Exhaust at point of use.
PROTECTIVE GLOVES :
  Gloves impervious to solvents.
EYE PROTECTION :
  Face shield.
OTHER PROTECTIVE EQUIPMENT :
  Evewash station.
  IMPERIVOUS CLOTHING & BOOTS
HANDLING AND STORAGE PRECAUTIONS :
  Overheating may cause container to rupture.
  EMPTY CONTAINERS CONTAINING RESIDUE MAY CAUSE A HAZARD.
  WASH THOROUGHLY AFTER HANDLING
  DO NOT TAKE INTERNALLY
  AVOID CONTACT WITH SKIN, EYES & CLOTHING
  AVOID BREATHING DUST OR MIST
  KEEP AWAY FROM FEED & FOOD PRODUCTS
  FOR MANUFACTURING USE ONLY
```

KEEP CONTAINERS COOL, DRY & AWAY FROM IGNITION SOURCES

Avoid prolonged breathing or contact with skin.

STORE IN COOL SHADED AREA

Check all containers for leaks.

OTHER PRECAUTIONS :